
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: <u>7/30/2009</u>
Test to be performed: Smoke Dyed Water X	Ground Condition: Dry ☑ Damp ☐ Wet ☐	Supervisor: JAW
Manhole_ID: S02WW_008MH	Test ID: <u>D1032-025011</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S01WW_007MH
0			Water Level	
0			Dye Test Visible	@ Tap - toilet
0			Dye Test Visible	@ Tap - downspout
0			End of Survey	